



## Jet Centro, Sheffield

Monthly Newsletter | External Wall Systems  
October 2021

Hello,

We hope this finds you and yours safe and well this Autumn! Welcome to this month's newsletter regarding the external wall system at Jet Centro and our progress to begin works on site to remediate the external wall system.

### *Building Safety Fund Application*

We continue to await an update from the Building Safety Fund following the technical eligibility submission of our application to the fund. While frustrating, it is unfortunately quite common for the process to take this period of time. We will be in touch once we have any correspondence from the fund to share.

### *Project Update*

Another report on the building is to be undertaken and is scheduled to take place on the 1st – 2nd November 2021. This survey will require opening up works to the building in areas that have been identified. This will provide us with a comprehensive assessment of the buildings structure and façade. The Property Manager will be directly contacting those who may be affected by the undertaking of the survey.

Thank you for taking the time to review our latest newsletter. As always, you can find copies of this and all previous newsletters [here](#).

You'll hear from us again next month, and if we have any big news to share before then, we will reach out. As always our team are on-hand to answer any questions at [BuildingSafety@liv-group.co.uk](mailto:BuildingSafety@liv-group.co.uk)

Thank you,

LIV Group

[Visit our Website for Updates](#)

[Click here to see a web page of the asset](#)

Copyright © 2021 LIV

All rights reserved.

%SENDER-INFO%

[See how to unsubscribe](#)